## ARIZONA DEPARTMENT OF WATER RESOURCES

## Office of Assured and Adequate Water Supply

3550 North Central Avenue, Phoenix, Arizona 85012 Telephone 602 771-8500 Fax 602 771-8689



Janet Napolitano Governor

Herbert R. Guenther Director

April 7, 2008

Mr. Roy Tanney Arizona Department of Real Estate 2910 N. 44th Street Phoenix, Arizona 85018

Water Report #53-700513.0000 Subdivision Name: Solomon's Lakes

Owner: Solomon's Manor, LLC an Arizona limited liability company

Number of lots: 56 County: Navajo

Township 11 North, Range 22 East,

Section 6

Water provided by: Dry lot, individual wells

Water Type: Groundwater

Current water depth: No Information provided Estimated 100-year depth: No Information provided Current decline rate: No Information provided

Basin: Little Colorado River Plateau

Dear Mr. Tanney:

Pursuant to A.R.S. § 45-108, the Department of Water Resources has reviewed the available information pertaining to the water supply for the above-referenced subdivision. This letter constitutes the Department's report on the subdivisions water supply as required by A.R.S. § 45-108(A).

Adequacy of the 100-year water supply was reviewed by the Department with regard to physical, legal and continuous availability, water quality, and financial capability. No information has been provided to the Department that indicates that the applicant has satisfied the adequate water supply requirements as set forth in A.A.C. R12-15-701 *et seq.* Therefore, the Department of Water Resources finds the water supply to be *inadequate* to meet the subdivision's projected needs.

Pursuant to A.R.S. §32-2181(F) a summary of the Department's report for those with an inadequate water supply be included in all promotional material and contracts for sale of lots in the subdivisions. We suggest the following synopsis:

"Solomon's Lakes subdivision is being served groundwater by individual wells. The developer has chosen not to demonstrate a 100-year adequate water supply. The applicant has not demonstrated that the criteria for physical, legal and continuous availability, water quality, and financial capability have been met. Therefore the Department must find the water supply to be *inadequate*. For additional information please contact Richard Obenshain, of the Office of Assured and Adequate Water Supply at (602) 771-8599."

The developer, pursuant to A.R.S. §32-2181(F), may suggest a different summary of this report, but it must contain the above elements and/or the Department's findings.

Pg. 2 April 7, 2008 Water Report Solomon's Lakes subdivision

This letter is being forwarded to your office as required by A.R.S. § 45-108. This law requires the developer to hold the recordation of the subdivision's plat until receipt of the Department's report on the subdivision's water supply. By copy of this report, the Navajo County Recorder is being officially notified of the developer's compliance with the law.

Sincerely,

Sandra Fabritz-Whitney

**Assistant Director** 

Water Management Division

cc: Navajo County Planning and Zoning

Navajo County Recorder Anthony E DePrima

Richard Obenshain, Office of Assured and Adequate Water Supply